Menlo Park Notebook #14 [N-78-12-31]

This notebook covers the period December 1878-February 1879. Most of the entries are by Edison, Charles Batchelor, and Francis Upton. A few entries are by Charles P. Edison and John Kruesi. Many entries are signed by Edison. Almost all of the material relates to experiments on electric lighting. There are notes and calculations about lamp and filament tests, including a numbered series cross-referenced to other notebooks; and notes, drawings, and calculations about generators, some similarly cross-referenced. There are also notes and drawings of the new receiver for the telephone. The book contains 288 numbered pages.

Blank pages not filmed: 4-5, 236-237, 280-285.


14
Full
From the Laboratory
of
T. A. EDISON.
MENLO PARK, N. J.
No. 14.
Magnet armature & winding arrangements p. 3
Tests of Spirals with varying no of cells. Jan 77. p. 30-45
Use of spirals in vacuum and various materials for making with experiments. Important and interesting. Feb. 77-143
Winding of Dynamo machine. p. 168-257
N-78
12-31
N-78-12-31


No 14
LIBRARY OF THE
BOARD OF PATENT CONTROL,
120 BROADWAY, NEW YORK.
No 14
1 turn = 73 inches 36 turns
2 turns = 73 " 17.75 turns
4 turns = 73 = 8 layers 8.625 turns
8 turns = 16 layers 4.06 turns
16 turns 32 " 1.78


No 14
No 14
Pages 1 to 2. "Dynamo Notes." (Unimportant)

16 | 94 | 59 | 16
8 | 6 | | 9
142 | 144
59 wires | 152
x3 | x3
177 | 456
41 | 13 | 1064
430 | 11096
359 | 925

Chat Spectator Dec 1878 3

New Magneto Machine

Armature



Diameter outside 3½
inside 3

This armature has ends of Vulcanized fibre bounded by discs as not to touch the wire



And one wire wound round it lengthwise and one end polished off so as to be used as a Commutator.

6

New Lecaister Dec 31st 1878
Chas. F. Edison



New Reciter Dec 31st 1878
Chas. L. Edison



friction feed.

when button (A) is dry there is greater friction which draws up screw (B) which elevates lever (C) with moist roller

New Receiver Dec 31st 1877 //

Thos. A. Edison



12

New Leaves Dec 31st 1874

Dec 31 1878





16



$R + B : B :: D : D_1$

$R D_1 + B D_1 = B D$

$B = \frac{R D_1}{D - D_1}$

$G + B + R : G + B + R_1 :: D_1 : D$

$(G+B) D + R D = (G+B) D_1 + R_1 D_1$

$G + B = \frac{R_1 D_1 - R D}{D - D_1}$

2

11

$$\frac{1}{R} = \frac{1}{R_1} + \frac{1}{R_2} = \frac{R_1 + R_2}{R_1 R_2}$$

$$C = \frac{\varepsilon}{R} \qquad C = \frac{\varepsilon}{\frac{R_1 + R_2}{R_1 R_2}}$$

$$= \frac{\varepsilon R_1 R_2}{R_1 + R_2}$$

$C_{total} : C_1 : C_2$ (totals) : R_2

$R + R + 9$ Dec 31 1979 19

$R + R_1 + 9$ 9

$R + \frac{R_1 + R_2}{R_1 R_2}$ $R_1 = 9$

$R_2 = 9 + R_3$

$R + \frac{9 + 9 + R_3}{9(9 + R_3)}$ $\frac{9}{2}$



20

Current in one arm

$C_1 : C_2 :: R_2 : R_1$

$C_{1\,total} : C_2 :: R_2 : R_{1\,total}$

$C_1 \quad C_2 \qquad \frac{1}{R} : \frac{1}{R_2}$

$$\frac{C}{C_2} = \frac{\frac{1}{R_1}}{\frac{1}{R_2}} = \frac{R_2}{R_1}$$

Dec 31 1898 21



$C = \frac{\mathcal{E}}{B + \mathcal{G} + R_1}$ Tick

$C = ?$

$$C_{total} = \frac{\mathcal{E}}{\frac{R_2 + R_3}{R_2 R_3} + B} = \frac{\mathcal{E} R_2 R_3}{R_2 + R_3 + B R_2 R_3}$$

$$\frac{C}{\frac{R_2^2 R_3}{R_2 + R_3}} = \frac{\mathcal{E} R_2 R_3}{R_2 + R_3 + B R_2 R_3}$$

$$C = \frac{\mathcal{E}(R_2 + R_3)}{R}$$

24

5 $\frac{9}{16}$



25

(7)











June 3rd 1879



30

1. 150 mm. ~~Pt~~ .004 wire
Iridium Pt alloy 20%
Spool No ~~#~~ 1
The wire stretched between
the two small wires

~~6.39~~

Cold 6.39 Ohms

Called. 7.15 on the steps
Without a shunt

2. Pt. 9 ad. the same as
No. 1. D= 40 .0392
R = 6.39
One cell carbon
same resistance cold
deflection 4° on steps
Called with shunt of [illegible]

3. Pt. 9ad same No. 1
2 cells Carbon
7.80 Ohms
6° deflection with
shunt as in 2 & 2
.0860
2.19 times.

324

4 Same as No 1

3 cells carbon

Bradley with shunt as in No. 2

8.1 Ohms

8°

9.147
9.147
.908
19202

log 0.159 — $\bar{1}.202$ — .159

$\bar{2}.593$

4.06 — .1609

Same as No. 4. Throw 3rd 5/33

4 cells carbon

8.8 Ohms

10° deflection Mr. B. thinks that this is just on the read very faint "fundamental glimmer.

9.246
9.246
.940
19436

log. 0.273 — $\bar{1}.436$

$\bar{2}.593$

.843 — 6.97

34

6 same as No 5

5 cells

Bright red No. 1

9.8 Ohms

D = 11°

9.288
9.288
.991
19 567
log 0.369 1.567
2 593
.974 9.42

1.567
1.436
.131 1.35
2.04

same as 6

6 cells

Bright red in diffused daylight, white covered

10.2 Ohms

D = 12° 30'

35

7

~~9.255~~
~~9.255~~
9.345
9.345
1.008
19 698

log 0.499 1.698
2.593
1.105
12.7

1.698
1.436
.262
1.85

1.698
1.567
.131
1.35

1.698
1.436
.262

36

same no 7

7 cells

Yellow red or orange look like $\frac{1}{32}$ in diameter

$\mathcal{D} = 13° 30'$ distance 2 ft.

$R =$ ~~[illegible]~~ Ohms

11.1 Ohms

	9.380	
	9.380	
	1.045	
	19.805	
log .639	$\bar{1}$.805	
	$\bar{2}$.593	
	1.212	16.2
	$\bar{1}$.805	
	$\bar{1}$.436	2.36
	369	
	238	1.73

same no 8

37

8 cells

Yellow and beginning of light "small" about $\frac{1}{6}$ light "looks at distance of two feet to be $\frac{1}{16}$ of inch thick. Lags $\frac{3}{8}$ in.

$\mathcal{D} = 14° 30'$

$R = 11.1$

	9.412	
	9.412	
	1.045	
	19.869	
log 0.740	$\bar{1}$.869	
	$\bar{2}$.593	
	1.276	18.9
	.433	2.71
	.302	2.0

38

9 cells

Quite white.

Appears a shade more than 1/10 at 2 feet

D = 15.0

R = 11.2

9,428
9,428
1,086
.875 7 942

1.349 22.3

.506 3.21

.375 2.38

39

10 cells

a good bright light, wire appeared to radiate a little, appeared no larger

D = 16°

R = 12.6

9,457
9,457
1,100
20,014

~~.875~~ 0,014

1,030 1.421 26.5

.578 3.79

.447 2.8

9.2 40

11 cells

with shade of yellow

White light the cusp seemed covered with fine lines

D = 17° 30'

R = 12.96

9,498
9,498
11,110

Log 1.28	.106		
	2.593		32.7
	1.513		
	T 1078		
	.670		4.68
	.106		
	1.567		3.48
	.539		

41 13

January 3rd 1919

12 cells

~~Brilliant~~ Full white

D = ~~15~~ 18° 30'

R = 13.26

9,524
9,524
1,122

1.47	.168		
	2.593		37.8
	1.575		
	.168		
	T 436		5.4
	.732		
	.168		
	1.567		3.98
	.601		

13 cells

Brilliant white

λ = 19° 30'

R = 13.56

9.549
9.549
1.132

1.70 .230
2.593
Cold 1.637

.230
1.436
.794

.230
1.567
.663

43.4
~~43.4~~
~~43.4~~
6.22
4.61

14 cells

Intense white as far as
washed

236
2.593
1.643 44.

λ = 19° 30'

R = 13.86

9.549
9.549
1.138

1.72 .236
Just Red 1.436
log 6.31 .800

Red .236
log 4.67 = 1.567
.669

No. 2 $D = 4°$

$R = 6.39$

C° M.

8.8xxx
2.xxx
.805
18.593
2.593 .0392

No. 3 $D = 6°$

$R = 7.8$

9,021
9,021
.592
18 934 .0860
2.934
2.593
.341 2.19

January 3rd 1919 [illegible]

when a 150 mm. bar of [illegible] is brought to maximum & permanent elongation ½ a mm due probably to being alternately [illegible]

If when measurements [illegible] the readings straight & regular & elongation [illegible] an initial vibration not easily found —

Measurements — [illegible] is an advantage [illegible] to have the light & will often a moment of quiet commence (a vibration of a tuned string) [illegible] a vibration of ⅛ of an inch upon a unit, when it ought by this effort [illegible]

The effect of this vibration is also to cool the iron producing Carbon below a blue light appears in the [illegible] of the unbent part

of vibration. January 3 1879

By the wire is bent 209 209 - 209
& the Current put on & off
with a rapid movement — the 209
209 jumps apart & remains suddenly
Coil is perfectly represented

At a distance of 15 feet the
Electromagnet will lookate by
3/16 of an inch above the

16 4/4 cells Carbon makes 5 30 ohms
.004 Just faint red. Stitches in the open air.

D = 10° 30′ with shunt
R = 30.86 ohms

The same as 16 with Calloid 4/17 cold.

Young 3′ 1873
J.Y.

R = 20.46
D = 22° 30′ on no 3. wire

1810 .000 Rh. Iridium 150 Mm

Rhod ≅ 2

Cold
1 colloid R = 6 ohms

19 1 cell Carbon

D = 4.

~~R = 6.7 ohms~~

R = 6.1

0.030

8,844
8,844
.826
18.514

8,844
8,844
.784
18.476
2.476

2 cells 2057

D = ~~5.745~~ 6°45' ~~9.000~~ ~~9.000~~

R = 6.7

9.073
9.073
.826
18972
2.972
2.476
.496

~~.826~~

0.0938 Gray? 1879 Tait

3.1

2023 cells

D = 9° 30'

R = 7.3 ohms

0.204

8.6

9.223
9.223
.863
19.309
1.309
2.476
.933

4 cells slightly red

-220-

D = 11°

R = 7.9

0.297

9.9

9.288
9.288
.597
19.173
1.173
2.476
.997

January 5 '23

TJR

2354

5 cells dull red

$\Delta = 13°$

$R = 8,5$

9,363
9,362
929
19.655

0.452

1,655

18,1

1,179

1,53

,182

6 cells red orange

$\Delta = 14°$

~~$R = 8,9$~~

$R = 8,731$

9.396
9.396
929
,947
19.733

0.541

T 733

18,1

1.257

1,82

.260

1.19

.078

D-24

2.5.56

7 cells Orange yellow
a slight wind may be seen by
squinting the eyes

D = 1.5"
R = 9.2

9.428
9.428
.963
19.819
1.819
2.476 22.2
0.660
1.343

1.473
.346 2.2.3

7.655 1.64
.164

8 cells Yellow
squinting little orange
D = 16 -
R = 9.16 Ohm

9.457
9.457
.982
19.896
1.896

.788

1.896
2.476 26.3
1.420

1.896
1.473 2.64
.423

1.896
1.655 1.74
.241

9 cells bright yellow
whitish yellow

Δ = 17° 30′
R = 10

9.498
9.498
1.
19 996
1.996

0.991

1.996
2.476 33.1
1.520

1.996
1.473 3,31
323

1.996
1.655 2.21
344

10 cells dull white
yellowish white
white yellow

D = 17° 30′
R = 10.3 Ohms

9.498
9.498
1.012
20 008

1.02
1.008
2.476 34.1
1.532

.008
1.473 3.43
.535

.008
1.655 2.26
.353

2960

11 cells both the same as candle E118

D = 19.

R = 10.5

9.536
9.536
1.021
20.093

1.24

.093

.093
2.474
1.617

41.4

.093
1.473
.620

4.17

.093
1.655
.438

2.74

12. A little yellower than candle G
Whiter than candle E 9 13.30

D = 19° 30'

R = 10.7

9.549
9.549
1.019
29.117
25.
D.117

1.34

.127
2.479
1.648

44.5

.127
1.473
.654

4.53

.127
1.655
.472

2.97

3/13/27

3 cells

a little yellower than candle 11 ohms distance

Bright White 5 ohms

N = 20'30'

R = 11 ohms

9572
9572
11041
20185

1.53

.185
2.476
1.709

51.2

.185
1.473
.712

5.16

.185
1.655
.530

3.39

14 cells

Filament of 15 cp 220 V

Brilliant White 5 ohms distance

The same as candle 11 distance

D = .210

K = ~~11.5~~ .1

placed side by side and it seemed whiter and 8 times easy by eye than Fuchs

11.5 Wire melted at 140 amps

9.558 in bench.
9.558
1.060
20226

.228
1.473 m.22
.755 day

5.69 times

.228
2.476
1.752

1.691

56.5

1.~~23~~ 1.6 ~~X~~
5.64

.228
1.655 m.23
.573

3.75 times

64 See sheet no 3

Pt wire .004 150 mm

1 cell D = 5.0

R = 4 ohms

8.9419
8.9419
.6020
9.5439
-1.4858
E. 8581

6.356

2 cells D = 8° 30'

R = 4.9

9.1744
9.1744
.6932
19.0420
-1.0396
-2.4858
E. 5532

0.12

3.56

3 cells D = 11°

R = 5.7

9.2456
9.2456
.7558
18.7470
-1.3330
-2.4858
E. 8472

.215

7.03

65

4 66 cells D = 13° ~~Dull red~~
R = 6.5

Dull red bells shown first column on No. 1 Test Sheets

9.3633
9.3633
.8129
19.5395
1.5395
2.4858
1.0537

.3461

11.3

5 cells Red

D = 14°
R = 7.2

9.3167
9.3167
.8129
19.4463
1.5395
2.4858
1.4942

.447

1.416

1.29

Jany 5 1879

67

6 cells Yellowish orange

$\Theta = 15^{\circ}\,30'$

$R = 7.9$

8.607

19.8

1.65

1.35

9.4429
9.4429
6976
1.9176 34

$\bar{1}.7824$
2.4852
1.2976

$\bar{1}.7824$
$\bar{1}.5395$
.2429

$\bar{1}.7824$
$\bar{1}.6501$
.1327

7 cells Yellow

$\Theta = 15^{\circ}\,30'$

$R = 8.3$

0.1638

20.8

1.84

1.42

[illegible]

[illegible]

[illegible]

70

8 cells Light bright Yellow

D = 17° 20'
R = 8.701

.869

28.3

2.51

1.94

9.47587
9.4987
.9415
9.93839
1.93859
2 .45858
1.45721
1.93859
2 .53295
.3994
1.93859
1 .65147
.2858

Whitish Yellow

9 cells

D = 18° 30'
R = 9.

1,101

33.1

2.02

2.26

9.52445
9.
.1961
20 .30581
08 .30581
2.49958
1.51983
.30581
1.53395
.4656
.30581
1.03507
.3544

Jany 5th 1874
TAE

10 cell Yellowknife White

D = 19° 2.01

R = 9.7

	9.5491
	9.5[illegible]11
	.9637
	29.0619
1.15	
	.0619
	-2.4858
37.7	1.5761
	.0619
	-1.5295
3.39	.5224
	.0619
	-1.6507
2.58	.4112

11 cells White

20° 30

R = 9.[illegible]

	9.5727
	9.5727
	.0777
	29.1231
1.328	
	.1231
	-2.4858
43.4	1.6373
	.1231
	-1.5395
3.83	.5836
	.1231
	-1.6507
2.97	.4724

172 cells Brought White

D = 21°
R = 9.9

9.58841
9.18441
.9956
2.01638

1.452

.1638
-2.45558
1.67780

47.6

-1.6378
-1.52398
.62433

4.22

1.638
1.6378
.51131

3.26

13 Brilliant white 75

D = 21° 30
R = 10.5

9.1958
1.0212
20.2217

1.643

-.2217
-3.48558
1.7359

54.4

-.2217
-1.52398
.68322

4.81

-.2217
1.0207
.5710

3.72

Jany 8, 1895

14 cells omitted

76

150

4 in = 100

6 in

.314
.004
.001256
6
.007536

.314
.004
.001256
6
.007536

.075) 1.000 (13
75
150

78 Iron lamps and 6 cells
D = [illegible] = 19°

R = .5 ohms both
Cold 1.2 ohms
9.5 369 The same ohms
9.5 369 as on Jan 14.
.69 69
19.7727
7.7727

.592

.2217
No. 3 .7727
.4490

White [illegible] wire No. 3. [illegible] gauge
[illegible] 2.8 more heat than red
2c. lamps with 1 in. surface

Jan 15.
Question how many lamps can be made to give 15 candles when nine gave

Three Iron lamps
all the cells of battery = 14
65° on No. 3 11.6 Ohms

3 2c. Lamps
D = 19° with shunt
2 2c. lamps. Thin surface
D = 21
R = 11. .02

14
.16
16.8

80

5°

8.9419
8.9419
0.7853
~~19.6691~~
~~1.6691~~
18.6491
2.5691

.46

6°

9.0216
9.0216
1.7853
19.8285
1.8285

.67

46) 346 (7.
322
240

67) 346 (5
335
11

2 ohm + B

16° = 0 + 10 = 17°

8° 30' + 1 = 9° 30'

$$C = \frac{\mathcal{E}}{R + B}$$

$$C_1 = \frac{\mathcal{E}}{R_1 + B}$$

$$C(R + B) = C_1(R_1 + R)$$

$$\frac{C_1 R_1 - C R}{C - C_1} = B$$

17 = C

9.5 = C_1

2 = R

4 = R_1

17 − 9.5 = 7.5

$$\frac{38 - 28.4}{7.5} = \frac{4}{7.5} = .53$$

.22 Ohm = R

1 Cell C, 2 Ohms in 42.5° = .932

C, R, 4 Ohms in 26° = .487

.487 × 4 = 1.948

.932 − 1.948 = −1.016

.932 × .487 = .454

.932 + .487 = 1.419

4.5 × 4 = 18.0

17 / 7.5 = 2.4

7.5) 4.00 (.53
    375
    .250

N_a R

82^0

.4 70^0 990

.4

396.0

$C = \frac{\epsilon}{R}$

$C_1 = \frac{\epsilon}{R+R}$

$CB = C_1B + C_1R$

$B = \frac{C_1 R}{C - C_1}$

tan 82°. 990

tan 70° .1939

.051

.396

Platinum wire .004

150 m m

14 ells Dull Red $6\frac{1}{4}^0$

Resistance 28 ohms

Reflect in Good as

11 Bent Ke[illegible]

Shaft bent down
Deflection 12°

Deflect 12

$W = \mathcal{E} q \qquad \mathcal{E} = C R$

$q = C t$

$W = C^2 R t = H$

$H = C^2 (\rho + r + \ell)$

$C = \dfrac{\mathcal{E}}{\rho + r + \ell}$

$H = \dfrac{\mathcal{E}^2}{\rho + r + \ell}$

Seven lamps in multiple are each 22 defici... estimated to have ... for 20 Ohms in ... 5 Ohms in 1

4 in R and ... in multiple

4 = 0

January 12 ...

Jr

90

1.243

8-51 P.M



75
2

150	0.176091
265	0.371454
205	0.271454
	.919997

524

3 lamps in multiples of
... batting rod lots

D = 51° 1.27

Rh lamps

2 - 64° 2.05

60

1.27 2.05

5/2 = 1.66
1.27
1.27

267

92

$\frac{1}{1.27}$ 2

2500

1 Ohm at 6.2°

2438

256

256) 2438 (9.5

2304

1346

1.6

3

4.8

1.27 2.05

1.27) 2.05 (1.6

1.27

780

762

18

$C = \frac{\varepsilon}{R}$

$1.27 = \frac{\varepsilon}{1.57}$ $1.57 = \frac{\varepsilon}{1.57}$

$C = \frac{\varepsilon}{1.57}$ Jan

$\frac{1}{1.57}$ $\frac{1}{1.27}$

1.27 1.57

1.27

$\frac{1.57 \times 1.57}{1.27 \times 1.27}$

$1.27 = \frac{1}{R^2}$ $1.57 = \frac{1}{R}$

$R = \frac{1}{1.27}$ $R = \frac{1}{1.57}$

1.27 1.57

$\frac{50}{10}$ 5 per H.P.

10002

1.1240

3,6
2
7.2

72 | 1.1240.0 | 1560
72
404
360
440
432
80

1.1240

7.2

Janry 12 1879

24.200.
5600

Feby 6 7 8 9 10th 1879

Experiments with cones in a Vacuum -

Platinum Iridium alloy 20pc Ir =

One Mechanical pump with $\frac{1}{100}$ of an

inch vacuum = Pt-Ir wire loses weight

= $\frac{1}{10}$ of a milligramme per hour, which

is deposited upon the glass - the surface

on which this loss occurs is about

1/4 of an inch. Resistance .75 of an ohm

Cold sign wire .020 of an inch

If the platinum wire is brought to a

dull red and the vacuum made

1/10 of an inch & allowed to remain

red for 1 minute & then made

yellow and the vacuum made perfect
again then were brought gradually
up making vacuum perfect after
each increment of heat the wire may
be brought to 21 candle power (10)
1/4 of such radiating surface will
give 21 C.P. the wire grows
exceedingly bright, swelling polished
silver and under the microscope
shows no cracks, when cool
brought to incandescence and then
it shows great cracks: I think

from our experiments that the
melting point is determined greatly
by the amount of gas within the
pores of the metal which by its
expansion disrupts the metal and
makes it fuse sooner. By gradually
increasing the heat the gas
gradually comes out of the metal
without disrupting & cracking
it. Roughly speaking I think
that if the melting point of
platina in the air by sudden
bringing to incandescence

i 2000 °C than something
point unrelated to at least
room C by subjecting it
to the process of annealing
it was by heat in a muffle
3½ Candle power until that
we have an engine of 1/4
for 1/4 inch in diameter
I think all metals to unalloyed
gr in their pure or even
other metals or metallic
have a lower melting point
& cause the unequal
Expansion disrupt the

Metals crack it thus 105
allowing it to fall on
Equipment to the b[illegible]

Feb 10 1849

Experiments with Steel
Pianoforte wire in vacuum
about .020 wire - 1/4 inch
radiating surface

We cooled one with cheese
water & dried [illegible]
Vacuum. Some of the elements
were brought to ~~boil~~
impure when to heat -
there was large amount

al: pallen oxide that was
from one turn to about —
cross connected; the evaporation
of the chalk makes quite arbonic
acid probably prevented the
oxidation = we have not tried
previously that pieces could
may be brought [illegible]
to give cobalt mixed with
but the oxide fumes has a
much lower melting point
than the steel thus if
Rockell W? excludes air the
gases have a 1.000.000 of

an atmosphere of nitrogen
& the iron wire [illegible]
we [illegible] brought to [illegible]
most dazzling [illegible]
we observed [illegible]
nothing & I do not think
there was any [illegible]

We now put in a spiral (
with lime in N_2O & drive
very little oxide formed but it
united steadily causing us
before the spiral = the lime
does not stink well but

Cakes off = of metals when the
melted & flowed where lime upon
it. Beautiful scales of
Violet & gold Calx probably
a Compound of Ammoniacal

We now put into a plain steel
spoon a Cake of each, & melted
out so turns more into a Cake
in Contact - & we continue
to raise the heat gradually
in 2 minutes we observed
a full white in a stinging
so high as to melt
parts somewhat

we now put in another sheet of opinel
with its convolutions further apart
to procure a greater variation in heat
at parts of the opinel - brought
it to steam which when it melted
in one spot showing a flaw there -
stained leaves of gold in all
parts before melting and there
been no flaw -
Procured
tried another piece brought
it up very gradually it was
coated with black or blue
Oxide with 2 coats
when it melted it went in
all parts at once

when change to say the
oxide vaporized on the glass
& left the whole of the
spiral which was incandescent
as bright as Silver.
I found that the brightness
was was entirely dependent
& could be hardened when
a part which was only dull
red was hardened by water
until it was as bright as
glass ——
We put Asbestos wire in
Atmosphere of Hydrogen.

if required a very much greater
Current to raise it to redness
and it melted at a much lower
white heat showing apparently
that the Hydrogen had more
influence on the [illegible] of
tion upon the metal
metal process
point as the iron itself
a vacuum yet the [illegible]
twice the light.
Perhaps there is
quantity of
in the atmo-
~~atmosphere~~ free. The

of the hypothetical ether -
thus accounting for the
diminished intensity of
the platinum in air as against
the vacuum; of course taking
into consideration the
gain due to crossing of
Convection Currents -

Put in new Spiral brought
to yellow white at 4.35-
PM on gramme machine -
added current 4.50 brought
to incandescence fused 4.52

Magnesium wire was brought to a dull red & fused melting on a vacuum hence the melting point as given in the books

(1) .447. Fahr or 230 C must be wrong or Draper is wrong in attributing 900 to a dull red =

We now put a Wrought iron spiral in and brought to yellow white and letting it gradually fall to dull red in 25 minutes

owing to polarization of the battery - ~~Walter~~ go to Rumpus ~~to~~ take battery off at 6.55. We keeping up vacuum - We brought it at 7.20. to a dozzling white by Grammie but in 1 minute it melted because we tried to bring it too high.

Feb. 10

Iron wire .020 in. in diam
wound in the coils
separated .060 in. The ~~heating~~
current was put on gradually
and an aside noticed before
red heat was reached. Taken out
and polished to see if the oxydation
could have arisen from the O in the iron
again freshly oxydized.

"The color of the flame
when the iron melted was
a strong violet" E
Line B. Fluint violet H.
It was white and scintillated
some moments before melting.
The Gramme machine was
used.

179

The wire when taken apart after furnace was found to have a very high polish

No. 2 Iron W Feby 10 '94
.020 in in diam
6 1/16 in length 12 turns
.060 ∠ separated on a mandrel

Filled with H pumped out
//////// 10 times
Immediately with less than
2 in vacuum the battery was
put on. The wire became
black. The Gramme machine
used Violet Martin. Ultra violet
Edison. Light blue ∠ lighter than
the blue of Sulphur B. Blue
of sulphur N. or light blue

Ex To try iron wire in H
must have it coated with lime
to see if the presence of H
has any effects. There seems
to be in the O-H blow pipe
another effect than simple
heat in producing the intense
light formed.

The wire wound close
and the spaces between the
coils filled with lime. In
air of H at Atmos. pressure
with the Gramme machine
and strong current the
spiral coils red. And even
when brought to fusion

By the other day Mr. E. tried a lb. some thin wire — duction cream a ~~coil~~ coil on bottom, on the secondary. The light was quite brilliant from a very small spark. This shows the fineness of the division.

on signs of the whiteness seen on the O H blow pipe

Ex. No. 4 Feb 10 P.M. Feb 10 1879 FBS

Of iron wire

A spiral covered with titanic acid made into paste by with alcohol.

The titanium oxide ~~mixed~~ with the wire and ~~heated~~ ~~strong~~ heated to a great extent the wire. The wire melts very [illegible] tanic. Peculiar smells are received when taken off. The wire very much harder after heating and plunging in water becomes very hard but not extremely brittle.

Ex. No. 5. The wire passed through the fingers when bent at right angles and could be felt to break with short sudden jerks.

July 10 1879 gas

Ex. No. 6.

Very fine wire.

It was very light and seemed to melt at once. I have worn no ventilators.

Ex. No. 7.

Wire .014 in. Very resilient sank slowly without breaking. No ventilators.

Feb 12 1874 Tat

Ex. No. 7. Wh contains chemically pure nickel. Forged heated ~~[illegible]~~ beg H. red hot. Rolled out hot until two inches long. Then cold until about fifteen inches, and .001 in thickness and 1/8 in. in width. Ends were put as near as possible to each other and the N forced many times between them.

Ex. No. 6. 3/16 wide

Do 15m about of N cannot be melted in Bunsen and with blowpipe. Faint signs of fusion probably of the Ex No 9 wire when made less wide.

Steel wire easily melted in same flame as No. 6

Ex. No. 10. Smaller wire than No. 9 easily melts.

Ex. No. 10. Rt foil same thickness as No 5 in same frame at 1879 Feb 12 Tps

Ex. No. 11 N & Rt and in the same frame nickel as No 10 and very little difference noted in their behaviour. Rt metal slightly and a slight reduction on the N.

Ex No 12 Iron wire rolled into sheet and held in Burnham disk of metal

Ex. No. 13 Held in Hon frame from Mr Burnham Dod

not melt but ~~not~~ became very brittle and probably changed with blank oxidem. Feby 12 1897 T.M.

Ex. No. 14. The N. foil covered in a spiral on a mandril Brooks very easily at very ~~a~~ first across the foil. A spiral tried in a vacuum. 1 1/4 in Did not blacken as much before becoming ~~so~~ Could be brought to incandescence. Found with yellow light. Slight violet B. Mine spread like Mg. afterwards. Feb 11 P.M.

Ex. No. 15. A piece of Nitrum was tried in same flame as No 14 did not melt. even on the carbon Forms a bright oxide.

40

Feb. 12 1878
Mr. B. tried a globe and found glass too thin Directions for Cl Book 47 to Pg 157-159

2 p.m.
Ex. No. 16 She came as No. 15 with small spiral tire on three colors when it fevers. Retired unwell to be true.

Feb 12 1877 TAS

The following forms of affidavits was used to introduce these wire in the examination
Book 9 Page 163
See Page 117 Book 13
Page 117 Book 4 Pg 61 62, 63
for proposed form 64, 67

from forms proposed for Guessler Tube to enhance size of
Book 13 Page 114 & 121
drawn by Mr. E —

142

Memorandum of

Feb. 12, 1878.

Coating Pt with oxides by decomposition of the Nitrates by means of heat.

Ex No. 17 Nitrate of zirconium does not coat the wire at bright red nor at dull red heat. Red at little for in it

Ex. No. 18 Zircon apparently contains Mercke's Zr. very infusible. melts instantly.

Ex No. 19 Nitrate Calcium coats the wire without apparently dulling it. Under microscope cracks all over but in globules and

penny thin between the [illegible] Particles of
[illegible] very impure. Spots could
be found which the coating did not
cover. Does not even blow
with much. Wire rubbed by
finger [illegible]
The coating of
heat. At penny [illegible]
good coating [illegible]
could be obtained by
through the coating.
The idea is to [illegible]
an excess to one of the
[illegible] The value of [illegible]
found the solution.
Used the wire
current [illegible]
[illegible]. Rubbed and then a [illegible]
@ perfect coating obtained
and the wire heated by

the sides of an uncoated one
and no difference seen in the
light. Does not seem to [illegible]
the melting point of [illegible]
[illegible] Same effect at high heat
The wire appears glowing
very brilliantly and
white. Nature said [illegible]

Ex. No. 19 Ascertain if [illegible]
radiant form can be
absorbed, when the [illegible]
heat just visible, [illegible]
from [illegible] with
Give more light when at full
heat because [illegible]
require less heat [illegible]
than to incandescence
the same way heat is

Rh wire becomes polished
by the melting of the fine
[illegible] its surface
it surface [illegible]
to [illegible] the [illegible] of
the main wire will magnify
it [illegible]. Hence [illegible]
[illegible] with
[illegible]
[illegible]
[illegible]

Feby 12 1877

Ex No 20 Acetate of Ammonia does not corrode the wire at any heat.

July 12 1879 Dec

Ex. No. 21 Acetate of Lime gives a very fine deposit of wire seemingly continuous under the most ~~[illegible]~~ ; I used ~~[illegible]~~ with much success for ~~[illegible]~~ to be used also. Lime ~~[illegible]~~ combine with the Ox. Magnesia ~~[illegible]~~ of course.

Ex. No. 22. N seems to have no effect other than the air when Pt. Spiral is heated in it and also in vacuum

~~Ex. No. 23.~~

Ex. No. 23. Tried Alcohol vapor could see no change

Ex. No. 24 filled globe with tobacco smoke & watch the air connection.

Ex. No. 25 Put a piece of paper in contact with the spiral so that it would burn [illegible] good connection

Ex. No. 26 Ammonia and Hcl tried with litmus paper and needle and put in the mix got good result.

Ex. No. 27 Spiral coated with
Acetate of magnesia in vacuum
Current put on at 3.30 P.M.
Very brilliant incandescence
Vacuum does not [illegible]
after about an hours running
when it ceased to shine. Spiral
left in open air.

The tip of the glass [illegible]
and the ends coated [illegible]
with a light precipitate after
being ~~the~~ in the air for some
time. No ~~[illegible]~~ change [illegible]
turned to be [illegible]

[illegible]
[illegible]
[illegible]

Spiral covered with rust

Ex. No. 28 8-30 P.M. Same spiral 137

12 1879 Feb

White 10-3

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

In the air for 24 hours

A thin black deposit noticed

whilst the platinum remained bright

so that none was [illegible]

directly behind the wire.

The wire was [illegible]

inside of the [illegible]

as the deposit was very much

less it is hoped [illegible]

pletely covering [illegible]

be [illegible]

Fct. 131878

Ex No. 28 The coating membrane
the microscope
organisms
[illegible]

Ex. No. 29. [illegible]
and no growth

Ex. No. 30. [illegible]
distilled water
Lime, magnesia,

Ex. No. 31 Nitrate of [illegible]
and distilled water

32 Nitbiuna melts [illegible]
attacks it feebly.

33 Pelam Grind and a good
early Potatoe

Onion Ng. Globe

Nitrochloride of tin

Sticks

Confined to bed

through a bath

Effects of Strontia Failure

Chloride of magnesium

Must be

injectible

Carnelian Magnesia does not
alter when [illegible]
Good covering when the [illegible]
white heat. When continued at
white heat in the [illegible]
Turning to crystals.
Calcium combines.
Value and use of magnesia in
the various kinds of [illegible]
off [illegible]
[illegible]
Ex. No. 34 Iron by H and the
temper [illegible]

Ex. No. 35 asbestos mixed
with magnesia [illegible]
mix.

Ex. No. 36 Feby 13 1879

The Edison dynamo machine





Feb. 14, 1879.
No 82





Feb 14 1879
TAE



Feb. 14 1879
TAE



17 Feb 14 1879.

Feb. 14 1879

17



172 Feb. 14 1879 KRUSE



Feb. 14 1879 KRUSE 173




Feb. 14 1879 Harlem
No 9.

Feb 14 1879



Feb. 14, 1879.



Feb. 14, 1879.



(80)



Feb. 14, 1879.

(81)



Feb. 11th 1879.

Fig 6



Electric Lamp

To utilize a current of small E.M.F. and large quantity, as that of a magneto-electric machine, for the production of a powerful electric spark from the Induction Coil.



Ex No. 37. Drum and Pt wire sealed in glass tubes. Mr Aprard exhibit.












196
97

198

feb. 16 1919



199

feb. 16, 1919



W-579
Toe




Feb 16 1979
Feb 16 1979



5

$\frac{1}{3}$ ohm

118 = 1

54 ohms



16·28 17·28
14·07 1
.514

25

26

54 coils of 74 turns of 20 wire take up 17·28 inches of shell

each coil ·16 both sides ·32

Diameter .514 17·28 inches

Feathers 4 ¼" inches

Available space for Coils 16·28 each ·32 = 51 coils

Will 51 coils do.

210

Feby 10 1892



2.12




Feb 16 1874
Feb 16 1874
1
2
3
4
5
6
7
8
1
2
3
4
5
6
7
8













Two ends left open 1. 7 8. Edison prefers
to fasten these two ends to two small commu-
tators as:-



228 Diam .005 in.

.005 in Rt. Platinum .005 3/4

600 mm. R = 8.7 Ohms

Diam .005 B.S. .005 in.

10% Rt. Iridium

600 mm. R = 17.4 Ohms

20% Pt. Iridium

Diameter .005 B.S.

600 mm. R = 15.4 Ohms

Feb 29 1899 JWG

Iron wire .015 + B.S.

60 mm. R = .62 Ohms

Iron wire .011½ B.S.

60 mm. R = .89 Ohms

Primary ○ .17 Ohms

Secondary 58 Ohms

□ Primary .41 Ohms

Secondary 142 Ohms

575^2

500

$500^2 : 575^2 :: 6.7 : ?$

575
575
2875
4025
2675
3306 25

3306
25)

1.32
67
924
792
8844

6.7 ohms

89
15)
445
89
133 5
810

3306
9
13216

62/9
5.58
11

6.7 ohms
8.8 ohms

30.
6
180

27 feet, 6 11. wire

4
108.
24
540
216
2700 (675
24
30
25

5.58
15
2790
558
8376

17
3

27. 6.

6 27

7


N
S
N
S
N
S
S
N

N
S

Feby 20 1879 Tar



Feby 20 1879 Tar

Edison Laboratory Note Book No. 14.

Page 225.

See Edison Patent:

370,128 (Pat. Sept. 21, 1887.)



Febyzo 1879 Tar







240

4 in. Quot.

$\frac{4\frac{1}{2}}{25} \quad \frac{1}{50}$

17.

$4\frac{1}{2} : 3 :: 25 : ans$

$4.5 \overline{)75} (17.$
45
300

15


S
N
N






12





450
92

450
6
2700

9 / 54000, 600



600
9
5400

4

120,

33

weight – 27 lb

diameter

1500 r

18.000

20.



215.

$\frac{1}{3}$

b = resistance

Let a = orig lamps

$\frac{a}{n}$ = multiples

$\frac{1}{a+b}$ = orig current

$\frac{1}{\frac{a}{n}+b}$ = multiple current

$\frac{\frac{1}{n}}{\frac{a}{n}+b}$ = current in each lamps

1997
998

$\frac{2000}{2001}$ .999

$\frac{1333}{1334}$

$\frac{1000}{1001}$

$\frac{800}{801}$

60

666.66
667.66

571.4
572.4

500
501

444.44
445.44

10 lamps

400
401

6021
6031 .997
.9990
.9980 .9955

15 lamps 4000

266.66
267.66 .9925
.992 .9929

20 lamps

200
201

21
.9979
.9958

.990

25 lamps

27
.9973
.9946

.987

262

32 lamps

125/126 — 35 — .9965 — 2 — .9930 — .984

40 lamps

10/11 — 0414 — 9586 — 2 — .9172 — .826

1656/828

100/101 — 43 — .9957 — 2 — .9914 — .980

4/5 — 6021 — 6990 — .9031 — 800 — 2 — .8062 — 640

1280/640 Table

20/1965 — .982 — Table

200 lamps

20 — .3010

21 — .32222 — .9788 — 2 — .9576 — .907

1814/907 Table

3000 — 2/3 — 3010 — 4771 — .8239 — 2 — .6478 — .444

1888/444

18½

19

36 inches 3 feet

99999 250 feet

3.15
85
1575
2520
26.775
.200
3387
134
67

67. commutator
divisions .200 for
wire

250
.200

67
3
201 feet around one wire
continuously

$\frac{170.6}{(.042)^2} = \frac{20.1}{x^2}$

1/4 #/m

20.1 2.3032 .045
42 2.6232
42 2.6232
comp 170.6 7.7681
17.3177
2.6588

.045

4 | 250
62.5
3
187.5

Core 8 3/4 / 8 3/4

26.77 1.4276
.187 1.2718
2.1558

143
71
2
213 feet

62.5
12.5
50

241.9 : 213 :: 25
25

213 2.3284
25 1.3979
241.9 7.6151
1.3414

21.9
.219 Ohms one turn

219
4
3 | 876
.292 Ohms

.049 75 commutator

8.75 9.25 9.5
9.5
1875
2
12 | 37500 inches
3125 feet

8.75 .9420 9.
3.16 .4997
1.4417

27.67

Make core
9 inches
62.5
2|2.75
1.375 1 3/8 inches iron

3.14
9
28.44

4|260
65
65
12 covers
53
.195

28.44 1.4539
.195 1.2900
2.1639

2|145.8
73

18
18.5
136.5
3.04
73
912
2129
2219 2 feet

241.9 : X :: 50² : 53²

241.9 2.383836
53 1.72432
53 1.72432
comp +5ro 6.60221
2.43443

2.38384
6.60221
8.98605-10

272 feet

272 : 221.92 :: 25 :

2.3462
1.3979
7.5654
1.3095

20.3
4
8.2
26.4 Ohms

.264 Ohms

73 coils wound 4 layers
wire .0503 in. in diameter wound
in in three

1268

67

12 covering

55

28.44 | 1.4537
2.07 | .3160

67
3
201

1.1377

137
68 Coils

3.04
68
2432
1824
206.72

8
898 57
55 1.7404
1.7404
2.6765

~~1111~~ feet
299 feet

299 : 206.72 :: 25

2.3154
9.3979 - 10
7.5235 - 10
1.2368

172
4
3 | 724
24.3 ohms

Machine wound

67 coils .055 wire
allowing .012 for covering
four layers of three wires
connected gives .243 Ohms

The thickness of wire
on armature .268 in.

68
4
272 turns

39
12
78
39
468 turns on No. 12

75 commutators

.049
.013
.062
3
.186

2).379
.189

75 Commutators

75 | 2844 | 37.9
225
594
525
690
167
47
13
34

304
75
1520
2128
228.00 feet

on Machine

in

23 m feet

75 Commutators

No. 18 Wire

Distance from
Iron core to
Face Armature

.3
62
3
.186
.19
.376

75
3
225 machine No. 4

702 Machine No. 182

702/225) 702 | 3.1
625
270

1/3 the No. of turns

.625 .7959
.468 .6702
.1257
.1464
.1257 .2718
.0414
.1671 147 Volts

.625 7
.468
140

216

.035 wire No. 20

118.5 feet 1/4 Ohm on machine

228 feet

228 / 114.5 / 1923

2.3579 / 2.0736 / 2843

4 | 189 / 47.25 / 35 / 1225

.481 Ohms on Machine
.12 Ohms one layer
4 wires side by side
2 layers
.24 Ohm resistance

035 / 47 / 2 / .094

75 / 2 / 150 turns

.094
.010
.040
.144
.047

144 | 468 (3.2
432
360
288
720

150 | 468 (3.1
450
180

47# | 28440 (605
282
240
300

1500 / 2205
3300


35
13
48
48
96
60
1.56
20
10
30
1/8 .125
1/32 .03125
1/64 .01562
.035
.013
.020
.010



148 : 12 = 74 :

148 — 1904 — 592 — 148 — 21924

141032
1411
283564
4250496
1133465
85504
1411832
5644328
14118320
19861291624